GARMIN

Navigation Data Alert 26198

TO: Users of the Garmin Navigation Database

DATE: November 5, 2026

CYCLE: 2611

AIRPORT: BGJN - ILULISSAT

LOCATION: Greenland

SUBJECT: Regular Supplement 16/26 was Received Late

PRODUCT AFFECTED

Cycle 2611 of the Garmin Navigation Database (effective 29 OCT 2026 to 26 NOV 2026) is affected.

NOTE

This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

The following traffic pattern turn direction is incorrect.

Table 1.

Airport	Runway	Correction
BGJN	Runway 24	The correct traffic pattern turn direction for runway 24 is right.

PILOT ACTION

Use the traffic pattern information with caution.

RESOLUTION

This will be corrected in the 2612 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to FlyGarmin.com and select "Aviation Data Error Report."