GARMIN

Navigation Data Alert 26197

TO: Users of the Garmin Navigation Database

DATE: November 5, 2026

CYCLE: 2611

AIRPORT: EDDM - MUNICH, EDQA - BAYREUTH, & EDBN - NEUBRANDENBURG

LOCATION: Germany

SUBJECT: Regular Amendment 11/26 Procedures Not Updated Due to Late Source

---

PRODUCT AFFECTED

Cycle 2611 of the Garmin Navigation Database (effective 29 OCT 2026 to 26 NOV 2026) is affected.

NOTE

This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

The following procedures and runways are out of date.

Table 1. Out Of Date Procedures

Airport	Procedures
EDDM	NDB RWY 26R
	NDB RWY 26L
	NDB RWY 08R
	NDB RWY 08L
	LOC RWY 26L
EDQA	RNP RWY 21
	RNP RWY 03
	SULU1W Departure

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to FlyGarmin.com and select "Aviation Data Error Report."

GARMIN

Navigation Data Alert 26197

Table 2. Out Of Date Runways

Airport	Runways
EDBN	RWY 09/27

PILOT ACTION

Do not use the listed procedures or runway information.

RESOLUTION

This will be corrected in the 2612 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to FlyGarmin.com and select "Aviation Data Error Report."