GARMIN

Navigation Data Alert 26218

TO: Users of the Garmin Navigation Database
DATE: November 24, 2026
CYCLE: 2612
AIRPORT: LKCS - CESKE BUDEJOVICE
COUNTRY: Czech Republic
SUBJECT: Czech Republic Regular Amendment 13/26 was Received Late

---

PRODUCT AFFECTED

Cycle 2612 of the Garmin Navigation Database (effective 26 NOV 2026 to 24 DEC 2026) is affected.

This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

The following procedure contains out of date information.

Airport	Procedure	Correction
LKCS	LOC RWY 27	The correct location of the step-down fix for the localizer only procedure is 2.5 DME from BW ILS/DME.

PILOT ACTION

Use the procedure with caution.

RESOLUTION

The procedure will be corrected in the 2613 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "Aviation Data Error Report."