GARMIN

Navigation Data Alert 26200

TO: Users of the Garmin Navigation Database

DATE: November 5, 2026

CYCLE: 2611

AIRPORT: LROP - HENRI COANDA

LOCATION: Romania

SUBJECT: Departure with Incorrect Speed Restriction

PRODUCT AFFECTED

Cycle 2611 of the Garmin Navigation Database (effective 29 OCT 2026 to 26 NOV 2026) is affected.

NOTE

This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

Departure with incorrect speed restriction.

Table 1.

Airport	Procedure	Correction
LROP	SOKR2K Departure	The correct speed at OP890 is At or Below 250 KIAS.

PILOT ACTION

Use the procedure with caution.

RESOLUTION

This will be corrected in the 2612 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to FlyGarmin.com and select "Aviation Data Error Report."