



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Owners of Record of G5000-equipped Beechcraft Model 400A aircraft
DATE: January 16, 2017

SUBJECT: STC ST01821WI G5000 System Software Version 2091.02 for G5000-Equipped Beechcraft Model 400A

CERTIFICATION APPROVAL: STC ST01821WI MDL Revision 6

COMPLIANCE

Mandatory

PURPOSE

G5000 System Software Version 2091.02 corrects a condition that can result in nuisance autopilot disconnects.

PRODUCTS AFFECTED

G5000-equipped Beechcraft Model 400A aircraft with System Software Version 2091.00 or 2091.01 are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.