



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered GTX 327 Owners

DATE: August 25, 2017

SUBJECT: GTX 327 Software Version 2.13 Now Available for Non-GX000 Integrated Flight Deck Installations Only

CERTIFICATION AUTHORIZATION: TSO Authorization

COMPLIANCE

Recommended: Garmin recommends that this Service Bulletin be incorporated in GTX 327 units (within the serial number ranges listed in the Products Affected section) that have a software version of 2.12 or prior at the owner's discretion, and is not warranty reimbursable.

PURPOSE

This Service Bulletin incorporates new unit software version 2.13 for the GTX 327.

PRODUCTS AFFECTED

This bulletin is applicable to GTX 327 units with Software Version 2.12 or previous software versions that use a Gillham based altitude encoder, and are not installed in a Garmin Integrated Flight Deck system (G1000, G1000H, G950, G900X, G500, G500H, G600, Cirrus Perspective™, and Embraer Prodigy® Integrated Flight Deck Systems). The GTX 327 current software version is displayed at power up, on the unit's front panel.

Software version 2.13 addresses an altitude reporting issue when using a Gillham based altitude encoder with GTX 327 (011-00490-00) serial numbers 83750922 to 83752847 or GTX 327 (011-00490-10) serial numbers 84000356 to 84000357. See serial tag on the side of GTX 327 units to determine serial number, or contact local Garmin dealer for assistance.