



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## SERVICE ADVISORY

NO.: 1684 Rev B

**TO:** Registered Garmin GTN 6XX/7XX, GTX 345, and Flight Stream 510 Owner and Operators  
**DATE:** October 2, 2017  
**SUBJECT:** Garmin GTX 345 FIS-B Weather Not Appearing on ForeFlight  
**Rev B:** Revised and combined pilot action and resolution

---

### **PRODUCTS AFFECTED**

GTN 6XX/7XX products (with software version 6.21) and GTX 345 products connected to ForeFlight through a Flight Stream 510 are affected.

### **ISSUE**

GTX 345 FIS-B weather will not appear on ForeFlight when connected through a Flight Stream 510/GTN 6XX/7XX.

### **PILOT ACTION/RESOLUTION**

This has been fixed in Flight Stream 510 Software Version 2.32 (or later) and GTN Software Version 6.30 (or later). Notification of revision to any Garmin STC(s) incorporating this corrective software will be provided under a separate notification.

© 2017 Garmin Ltd. or its subsidiaries.  
This work is licensed under a  
Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.