



**AVIATION SERVICE DOCUMENT NOTIFICATION**

**TO:** Owners of Record of GTR 225/GNC 255 Products  
**DATE:** October 12, 2017  
**SUBJECT:** GTR 225/GNC 255 Display Software Version 2.20, COM Software Version 2.30, and NAV Software Version 6.03  
**CERTIFICATION APPROVAL:** TSO Authorization

**COMPLIANCE**

Optional

**PURPOSE**

Display Software Version 2.20, COM Software Version 2.30, and NAV Software Version 6.03 contains the following changes:

- Add ability for dealer to enable/disable a NAV receiver rotorcraft modulation filter.
- Add ability for dealer to adjust the COM radio carrier squelch.
- Prevent intercom status updates while COM radio is transmitting.
- Reduce the occurrence of NAV Needs Service messages due to transient events.

**PRODUCTS AFFECTED**

The units listed below with display software version 2.12 or earlier are affected by this bulletin.

<b>Model</b>	<b>Appliance P/N</b>
GTR 225	011-02718-00
GTR 225A	011-02807-00
GTR 225B	011-02808-00 011-02808-20
GNC 255A	011-02806-00
GNC 255B	011-02719-00 011-02719-20

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.