



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

SERVICE ADVISORY

NO.: 1765 Rev A

TO: Registered G900X, G950, G1000, Cirrus Perspective®, and Embraer Prodigy® Owners and Operators
DATE: November 20, 2017
SUBJECT: Collapsed Airways

PRODUCTS AFFECTED

G900X, G950, G1000, Cirrus Perspective®, and Embraer Prodigy® with GDU software versions 13.00 through 15.23 are affected

ISSUE

Do not select a Direct-To waypoint from a collapsed airway on the Flight Plan page. Selecting a Direct-To waypoint from a collapsed airway might result in an incorrect waypoint.

RESOLUTION

This issue is fixed in GDU Software Versions 15.24 and later.

© 2017 Garmin Ltd. or its subsidiaries.
This work is licensed under a
Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.