



GARMIN®

Navigation Data Alert

DATE: 12 February 2018
CYCLE: 1802, Effective 1 FEB 2018 to 1 MAR 2018
SUBJECT: Missing Fix on Airway

DESCRIPTION

Garmin has been made aware that the following airway contains a missing waypoint.

Airway	Error
V122	CEXUN waypoint is missing from the airway. It lies between OBRIN and CONLI waypoints.

This alert applies to the 1802 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION:

Use the airway with caution.

RESOLUTION:

The airway will be correct in the 1803 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."