



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

SERVICE ALERT

NO.: 1818 Rev B

TO: Garmin aera® 660 and D2™ Bravo/Charlie Owners and Operators

DATE: May 16, 2018

SUBJECT: Degraded GPS Performance

REVISION B: Added the D2 Bravo

PRODUCTS AFFECTED

Garmin aera 660 products with main software 3.20 (and earlier), D2 Bravo with GPS software version 3.10, (and earlier), and D2 Charlie with GPS software version 4.30 (and earlier) are affected.

To check the D2 Bravo and Charlie GPS software version go to the About page (Settings->System->About) and scroll down to display the GPS software.

The aera 660 main software version can be viewed below the Garmin logo on the power up screen.

ISSUE

The aera 660 and D2 Bravo/Charlie may not be able to acquire a 3-D GPS position fix and/or exhibit degraded GPS performance.

PILOT ACTION

Connect the device to a wifi signal and download the latest unit software. For instructions on loading the latest software refer to the Garmin aera 660 Pilot's Guide (190-02017-20), D2 Bravo Owner's Manual (190-01674-00), and/or D2 Charlie Owner's Manual (190-02236-00). All manuals can be found on www.garmin.com.

The aera 660 software can also be downloaded from the Garmin website (<https://buy.garmin.com/en-US/US/p/520775>).

RESOLUTION

This issue has been fixed in D2 Bravo GPS software version 3.30, D2 Charlie GPS software version 4.40, and aera 660 main software version 3.30.