



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered Garmin GFC 600 Owner and Operators
DATE: May 1, 2018
SUBJECT: GFC 600 update for new Roll Servo Brackets and GMC 605 Software Version 2.11 for Textron Aviation (Beechcraft) models 36/A36/A36TC
CERTIFICATION APPROVAL: STC SA01844WI

COMPLIANCE

Mandatory for GFC 600 systems installed per GFC 600 Part 23 AML STC SA01844WI, Master Drawing List 005-01009-01, Revision 1 or 2.

PURPOSE

Notification of STC approval for installation of new roll servo brackets and new GMC 605 software in Textron Aviation (Beechcraft) 36/A36/A36TC model aircraft

PRODUCTS AFFECTED

Textron Aviation (Beechcraft) 36, A36, and A36TC aircraft with GFC 600 systems installed per GFC 600 Part 23 AML STC SA01844WI are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.