



## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Registered Garmin GWX 68 Owner and Operators  
**DATE:** August 20, 2018  
**SUBJECT:** GWX 68 Software Version 2.20 for Non-GX000 Integrated Flight Deck Installations Only  
**CERTIFICATION APPROVAL:** TSO Authorization  
TSO/ETSO authorization does not provide installation airworthiness approval. Separate installation airworthiness approval is required for type certified aircraft. Notification of revision to any Garmin STC(s) will be provided under a separate service bulletin.

### COMPLIANCE

Optional: This Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

### PURPOSE

GWX 68 software version 2.20 improves voltage monitoring and handling of aircraft power supply transient voltages. GWX 68 software version 2.20 is also the minimum GWX 68 software version needed for G500 TXi and G600 TXi installations.

### PRODUCTS AFFECTED

GWX 68 units with software version 2.12 (or earlier) and interfaced to a G500/G600, G500 TXi/G600 TXi, GTN 7XX, GMX 200, or other 3<sup>rd</sup> party flight display systems are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.