

# GARMIN<sup>®</sup>

## Navigation Data Alert

**DATE:** 01 October 2018  
**CYCLE:** 1810 & 1811, Effective 13 SEP 2018 to 08 NOV 2018  
**SUBJECT:** Incorrect Missed Approach Turn Direction

---

### **DESCRIPTION**

Garmin has been made aware that the following procedure was delivered with an incorrect turn direction in the missed approach portion of the procedure:

<b>Airport</b>	<b>Procedure</b>	<b>Error</b>
KLNR	VOR-A (VORA)	The procedure delivered depicts an incorrect right turn to LNR VOR/DME

This alert applies to the 1810 & 1811 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

### **PILOT ACTION**

Use the procedure with extreme caution

### **RESOLUTION**

The procedure will be corrected in the 1812 cycle of the Garmin Navigation Database.

### **THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE**

*Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [fly.garmin.com](http://fly.garmin.com) and select "[Aviation Data Error Report](#)."*