



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GPS 150XL Owners of Record
DATE: October 16, 2018
SUBJECT: Discontinued Repair Service for the GPS 150XL

PRODUCTS AFFECTED

The GPS 150XL is affected.

DISCUSSION

Effective 12/31/18, ALL repair services and service parts for the GPS 150XL will be discontinued. As a reminder GPS 150XL display repair services have been discontinued since 9/1/15. Additionally (and effective immediately) NOH GPS 150XLs are also discontinued.

We sincerely regret discontinuing service or support on any Garmin product. However, a number of components required for the manufacture and/or repair of the GPS 150XL are no longer available.

Please visit www.Garmin.com/aviation for your product replacement needs.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.