

DATE: 13 November 2018

CYCLE: 1812, Effective 08 NOV 2018 to 06 DEC 2018

SUBJECT: Incorrect LPV Data

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with erroneous data defining the final approach portion of the following procedure:

Airport	Procedure	Error
CL53	COPTER RNAV (GPS) 347 (R347)	The LPV was delivered with erroneous data defining the final approach portion for the procedure.

This alert applies to the 1812 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Do not use the procedure in cycle 1812.

RESOLUTION

The procedure will be corrected in the 1813 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "Aviation Data Error Report."