



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Garmin G5000 Owner and Operators  
**DATE:** November 19, 2018  
**SUBJECT:** G5000 System Software Version 2091.04 (including GIA 64E Software Version 2.02.2) for G5000 Textron Aviation Model 400A (STC ST01821WI)  
**CERTIFICATION AUTHORIZATION:** STC ST01821WI

---

### **COMPLIANCE**

**Recommended** for G5000-equipped Textron Aviation Model 400A with G5000 System Software Version 2091.03 and GIA 64E hardware.

### **PURPOSE**

G5000 System Software Version 2091.04 (including GIA 64E Software Version 2.02.2) fixes a nuisance AP/YD FAIL CAS message on the MFD CAS window and an amber RUD BST FAIL Master Annunciator Panel illumination following an unsuccessful completion of the AFCS PFT, as described in Garmin Service Advisory 1842.

### **PRODUCTS AFFECTED**

G5000 systems with System Software Version 2091.03 and GIA 64E hardware installed in Textron Aviation Model 400A (Beechjet) aircraft using STC ST01821WI are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.