

FliteCharts Data Alert

TO: Users of all Garmin aviation products and Garmin Pilot using the US or North America FliteCharts database

DATE: January 9, 2019

CYCLE: 1901

SUBJECT: Corrected Airport Diagram for General Mitchell Intl (MKE), Milwaukee, WI

DESCRIPTION

The FAA has advised Garmin that the digital-Terminal Procedures Publication, effective January 3, 2019, incorrectly depicted information on the AIRPORT DIAGRAM at General Mitchell Intl (KMKE), Milwaukee, WI. The airport diagram shows the incorrect depiction of taxiway S between runway 1L-19R and runway end 1R, and does not show the taxiway pavement.

The original safety alert can be seen at the following link:

https://www.faa.gov/air_traffic/flight_info/aeronav/safety_alerts/media/TERM_19-02_SA_1901_MKE_AD.pdf

PILOT ACTION

Do not use the airport diagram at General Mitchell Intl (KMKE), Milwaukee, WI with cycle 1901 US or North America FliteCharts.

RESOLUTION

The missing information will be included in the 1902 cycle of the US and North America FliteCharts databases for applicable Garmin aviation products and in Garmin Pilot.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE US OR NORTH AMERICA FLITECHARTS DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."