



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin G1000 and G1000 NXi equipped King Air 200/300 Series Aircraft owner and operators
DATE: April 30, 2019
SUBJECT: G1000 NXi Update for G1000-equipped King Air 200/300 Series Aircraft
CERTIFICATION AUTHORIZATION: STC SA01535WI-D

COMPLIANCE

Optional: This Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

This revision includes a G1000 NXi update for legacy G1000-equipped King Air 200/300 series aircraft. System Software Version 2286.07 contains general robustness improvements and bug fixes for G1000 NXi-equipped King Air 200/300 series aircraft.

PRODUCTS AFFECTED

All Textron Aviation Inc. (Beechcraft) King Air 200 and 300 series aircraft equipped with G1000 Integrated Flight Deck per STC SA01535WI-D with the following system software versions are affected:

- software versions 0985.00 or later (legacy)
- software versions 2286.00 to 2286.06 (NXi)

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.