



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GPS 175, GNX 375, GNC 355, and GNC 355A Owner and Operators
DATE: August 14, 2019
SUBJECT: Approval of GNC 355 GPS/Comm Radio in an Approved Model List of Part 23 Aircraft
CERTIFICATION AUTHORIZATION: STC SA02636SE MDL Revision 5

COMPLIANCE

Optional: This STC Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

MDL revision 5 includes the following changes:

- Added the GNC 355 and GNC 355A to the STC
- Updated the GPS 175 and GNX 375 to main software version 3.02:
 - Corrected incompatibility issue with KI 208A and KI 209A
 - Corrected issue for GNX 375 with use of "Generate ICAO from Tail" in config mode, feature will now correctly calculate ICAO address
 - Changed default of user fields on the map to combined DTK/TRK (Desired Track / Track) in top right and DIS/BRG APT (Distance/Bearing from Destination Airport) in bottom right

PRODUCTS AFFECTED

GPS 175, GNX 375, GNC 355, or GNC 355A installed under the GPS 175/GNX 375/GNC 355 Part 23 AML STC SA02636SE are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.