



GARMIN®

Navigation Data Alert

DATE: 30 September 2019
CYCLE: 1911, Effective 10 Oct 2019 to 06 Nov 2019
SUBJECT: Military Procedures Not Updated

DESCRIPTION

Garmin has been made aware that the following procedures were not updated to reflect the latest amendment.

Airport	Procedures	Error
KNIP	TACAN RWY 10	Procedures not updated for the 1911 cycle.
	TACAN RWY 28	
	RNAV (GPS) Z RWY 10	
	RNAV (GPS) Z RWY 28	

This alert applies to the 1911 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Do not use the procedures in any manner

RESOLUTION

The procedures will be corrected in the 1912 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."