



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GDL 82 Owner and Operators
DATE: October 11, 2019
SUBJECT: Approval of GDL 82 main software version 2.01, GPS/SBAS software version 7.0, and added GPS 175 and GNC 355 as GPS position sources

CERTIFICATION AUTHORIZATION: STC SA02573SE

COMPLIANCE

Optional: This STC Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

This STC Service Bulletin provides notification for an update to the GDL 82 Part 23 AML STC SA02573SE. Major details of the update are:

- Updated GDL 82 main software version to 2.01, for anonymous mode improvements
- Updated GDL 82 GPS/GBAS board software version to 7.0



NOTE

GPS/GBAS software version 7.0 provides no functional change.

- Added GPS 175 and GNC 355 GPS navigators as acceptable GPS sources for the GDL 82

PRODUCTS AFFECTED

GDL 82 ADS-B datalink units installed using Part 23 AML STC SA02573SE are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.