



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin G1000 NXi-equipped Textron Aviation Citation Mustang Owners and Operators

DATE: November 18, 2019

SUBJECT: FS 510 software version 2.5() and G1000 NXi software version 0413.42 for Textron Aviation Model 510 Citation Mustang aircraft

CERTIFICATION AUTHORIZATION: STC SA01896WI

COMPLIANCE

Optional: This Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

This Service Bulletin announces the approval of Flight Stream 510 software version 2.5() and G1000 NXi system software version 0413.42 in Textron Aviation Citation Mustang aircraft.

Flight Stream 510 software version 2.5() provides enhancements and fixes to address connectivity issues with Portable Electronic Devices.

G1000 NXi System Software version 0413.42 provides the following enhancements:

- Incorporate configuration changes to eliminate nuisance database messages for un-used features. Changes include:
 - Ability to disable IFR/VFR Charts feature
 - Ability to disable Dual Charts feature
 - Ability to disable Electronic Chart feature
- Correct software and configuration loading sequence to GTX 345R ADS-B Transponder

PRODUCTS AFFECTED

G1000 NXi-equipped Textron Aviation Citation Mustang aircraft under STC SA01896WI are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.