



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GFC 600H Owners and Operators
DATE: May 6, 2020
SUBJECT: GMU 44B installation approval, GTN Xi interface approval, and the addition of the AY610 PMA stiffener for yaw installations
CERTIFICATION AUTHORIZATION: AML STC SR02647SE

COMPLIANCE

Optional: This STC Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

This STC Service Bulletin provides notification of an update to STC SR02647SE Master Drawing List revision 2.

Updates include:

- Installation approval of the GMU 44B magnetometer
- Interface approval of the GTN Xi Series navigators
- Addition of the AY610 PMA stiffener to the Garmin supplied STC installation kit

PRODUCTS AFFECTED

GFC 600H systems installed under the GFC 600H Part 27 STC SR02647SE in Airbus Helicopters AS 350 B2 and B3 models are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.