

GARMIN[®]

Navigation Data Alert

DATE: 04 May 2020
CYCLE: 2005, Effective 23 Apr 2020 to 21 May 2020
SUBJECT: Incorrect Turn Direction on Hold

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with an incorrect turn direction on the missed approach hold due to a change not being published in source:

Airport	Procedure	Error
CYCH	RNAV (GNSS) RWY 27 (R27)	The Missed approach hold direction was changed from Left to Right

This alert applies to the 2005 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Use the procedure with extreme caution

RESOLUTION

The procedure will be corrected in the 2006 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."