



## FliteCharts Data Alert 2089

**TO:** Users of all Garmin aviation products and Garmin Pilot using Australia FliteCharts database

**DATE:** July 17, 2020

**CYCLE:** 2008

**SUBJECT:** Incorrect charts related to Sunshine Coast Airport (YBSU) Expansion Project (SCAEP)

---

### **DESCRIPTION**

The AERODROME CHART PAGE 1, AERODROME CHART PAGE 2, APRON CHART, and NOISE ABATEMENT PROCEDURES charts at Sunshine Coast Airport (YBSU), Queensland, Australia incorrectly display charts related to SUP H41/20. SUP H41/20 has been cancelled. This affects Australia FliteCharts databases for cycle 2008.

### **PILOT ACTION**

Do not use the AERODROME CHART PAGE 1, AERODROME CHART PAGE 2, APRON CHART, and NOISE ABATEMENT PROCEDURES charts at Sunshine Coast Airport (YBSU), Queensland, Australia in Australia FliteCharts.

*Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.*

### **RESOLUTION**

The corrected charts will be included in the 2009 cycle of the FliteCharts databases. Cycle 2009 FliteCharts databases are effective August 13, 2020 and will be available August 11, 2020.

**WE STRONGLY URGE THIS INFORMATION BE MADE AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

*Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](http://FlyGarmin.com) and select "Aviation Data Error Report."*