

GARMIN[®]

Navigation Data Alert

DATE: 08 July 2020
CYCLE: 2007 & 2008 Effective 18 JUN 2020 to 13 AUG 2020
SUBJECT: Incorrect Missed Approach Hold Turn Direction

DESCRIPTION

Garmin has been made aware that due to an error in source, the following procedure was delivered with an incorrect missed approach hold turn direction:

Airport	Procedure	Error
25TN	Copter RNAV (GPS) 235 (R235)	The missed approach at LALLS WP was delivered with a right turn. The correct turn direction is a left turn.

This alert applies to the 2007 & 2008 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Use the procedure with extreme caution

RESOLUTION

The procedure will be corrected in the 2009 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."