

SERVICE ADVISORY

NO.: 20114 Rev A

TO: GI 275 Owners and Operators
DATE: October 15, 2020
SUBJECT: FIS-B NOTAMs

PRODUCTS AFFECTED

GI 275 products with software versions 2.10 and 2.11 are affected.

ISSUE

FIS-B NOTAMs do not appear on the weather page.

ACTION

Always refer to current aeronautical charts and NOTAMs for verification of displayed aeronautical information. Displayed aeronautical data may not incorporate the latest NOTAM information.

Information obtained solely through FIS-B does not replace a thorough preflight briefing. NOTAMs received via FIS-B uplink may not be a complete listing. Active NOTAMs are removed from the FIS-B data stream 30 days after issuance. FIS-B uplink is not an FAA approved source for NOTAMs.

RESOLUTION

This will be fixed in a future software release.