



!! URGENT !!

Date: 6 October 2020

Subject: Fresno, California
Fresno Yosemite Intl (KFAT)
ILS Y or LOC Y Rwy 29R
ILS Y Rwy 29R SA CAT I
ILS Y Rwy 29R CAT II & III
Cycles 2010 & 2011

Missed Approach Course Incorrect

Jeppesen NavData for cycle 2010, effective 10 September 2020, and cycle 2011, effective 8 October 2020, contains an incorrect course to the missed approach hold fix NIVEE/D8.0 FRA.

The course to the missed approach hold fix NIVEE/D8.0 FRA should be **042 degrees**.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2012, effective 5 November 2020. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

Please refer to the Fresno Yosemite Intl (KFAT) ILS Y or LOC Y Rwy 29R (11-2); ILS Y Rwy 29R SA CAT I (11-2B); ILS Y Rwy 29R CAT II & III (11-2A) charts dated 4 OCT 19, effective 10 October 2019, for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.