



**JEPPESEN<sup>®</sup>**  
**NavData<sup>®</sup> Alert**

**!! URGENT !!**

**Date:** 8 October 2020

**Subject:** Lam Dong, Vietnam  
Lien Khuong (VVDL)  
HONGA 2G [HONG2G]  
KANAM 2G [KANA2G]  
DILIG 2G [DILI2G]  
Cycle 2011

***Procedures missing from database***

Jeppesen NavData for cycle 2011, effective 08 October 2020, contains incorrect data for Lien Khuong Airport; Lam Dong (VVDL). Procedures **HONGA 2G [HONG2G]**, **KANAM 2G [KANA2G]**, **DILIG 2G [DILI2G]** are missing from the database. DAP SUP C18-20, effective 12 OCT 20 was received after the ICAO specified date for aeronautical information publication.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2012, effective 05 November 2020. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Lam Dong (VVDL) **10-2B chart dated 16 OCT 20** for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
+1-303-328-4445 (Western Hemisphere)  
+49 610 250 8175 (Eastern Hemisphere)  
E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.