

FliteCharts Data Alert

TO: Users of all Garmin aviation products and Garmin Pilot using the Australia FliteCharts database
DATE: December 7, 2020
CYCLE: 2013
SUBJECT: Karratha Airport (YPKA) Revised RNAV Procedures

DESCRIPTION

Airservices Australia has advised Garmin that the revised RNAV procedures at Karratha Airport (YPKA), Western Australia, Australia detailed in SUP H127/20 and included in FliteCharts cycle 2103, effective December 3, 2020 have been replaced with new revised RNAV procedures. The AIP supplement H134/20, effective December 3, 2020, cancels H127/20, effective December 3, 2020.

The original AIP supplement and corrected charts can be seen at the following link:

<https://www.airservicesaustralia.com/aip/current/sup/s20-h134.pdf>

PILOT ACTION

Do not use the RNAV-U (RNP) RWY 08 and RNAV-U (RNP) RWY 26 charts at Karratha Airport (YPKA), Western Australia, Australia in Australia FliteCharts.

RESOLUTION

The revised charts will be included in the 2014 cycle, effective December 31, 2020, of the Australia FliteCharts databases for applicable Garmin aviation products and in Garmin Pilot.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE AUSTRALIA FLITECHARTS DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."