

FliteCharts Data Alert

TO: Users of all Garmin aviation products and Garmin Pilot using the US, Canada, or North America FliteCharts database

DATE: December 25, 2020

CYCLE: 2013 & 2014

SUBJECT: Modifications for RNAV 36 at George M. Bryan, Starkville, MS (KSTF) are not charted.

DESCRIPTION

The FAA has advised Garmin that the digital-Terminal Procedures Publication, effective December 3, 2020 and December 31, 2020, is missing intended modifications for George M. Bryan, (KSTF), Starkville, MS.

The original safety alert can be seen at the following link:

https://www.faa.gov/air_traffic/flight_info/aeronav/safety_alerts/media/TERM_20-16_SA_STF_R36.pdf

PILOT ACTION

Do not use the chart for RNAV 36 KSTF within FliteCharts. Refer to the corrected chart at the FAA link above.

RESOLUTION

The charts will be corrected in the 2101 cycle, effective January 28, 2021, of the US, Canada, and North America FliteCharts databases for applicable Garmin aviation products and in Garmin Pilot.

FAA Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE US, CANADA, OR NORTH AMERICA FLITECHARTS DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."