

## **SERVICE ADVISORY**

**NO.: 2077 Rev C**

**TO:** GTN 625Xi/635Xi/650Xi Owners and Operators  
**DATE:** January 12, 2021  
**SUBJECT:** Replying to an SMS Text Message  
**REVISION C:** Updated Resolution

---

### **PRODUCTS AFFECTED**

GTN 625Xi/635Xi/650Xi products with Software Version 20.01, installed with a GSR 56 are affected.

### **ISSUE**

The send button is missing when replying to an SMS message received through a GSR 56.

### **ACTION**

Be aware the send button is missing when replying to an SMS message.

### **NOTE**

The ability to compose and send a new SMS message is not affected by this issue.

### **RESOLUTION**

This issue has been corrected in GTN Xi Main Software Version 20.11. Refer to Garmin TSO Service Bulletin 2102.