



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

#### AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Garmin G5000-equipped Textron Aviation Inc. Model 560XL Owners and Operators

**DATE:** March 2, 2021

**SUBJECT:** G5000 System Software version 3343.02 for G5000-Equipped Textron Model 560XL

**CERTIFICATION AUTHORIZATION:** STC ST01918WI MDL Revision 14

---

#### COMPLIANCE

**Mandatory:** This STC Service Bulletin must be accomplished within 180 calendar days or the next scheduled service interval; whichever occurs first.

#### PURPOSE

G5000 System Software Version 3343.02 improves and smooths autopilot pitch axis response with large VNAV flight path changes.

#### PRODUCTS AFFECTED

G5000-equipped Textron Model 560XL aircraft with System Software Version 3343.01 are affected.



#### **NOTE**

*This STC Service Bulletin is not applicable to G5000-equipped aircraft with System Software Version 3343.00.*

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.