



!! URGENT !!

Date: 3 June 2021

Subject: Controlled Airspace Boundaries
Cycle 2106

Missing Airspace Boundaries

Jeppesen NavData for cycle 2106, effective 17 June 2021 does not contain some Controlled Airspace records. On 20 May 2021 Jeppesen issued an Advanced Notification of NavData output change for the implementation of new Controlled Airspace types. Specifically, some boundaries which had been provided as Special Rules Areas (SRA) were changed to either a Radio Mandatory Zone (RMZ) or a Transponder Mandatory Zone (TMZ) in the 2106 cycle prior to customers updating their systems to accept RMZ and TMZ boundaries.

The following boundaries are missing from Jeppesen cycle 2106 NavData:

- Strausberg (EDAY) SRA
- Bydgoszcz (EPBY) SRA
- Lublin (EPLB) SRA
- Lodz (EPLL) SRA
- Rzeszow (EPRZ) SRA
- Szczecin (EPSC) SRA
- Olsztyn-Mazury (EPSY) SRA
- Warsaw (EPWA) SRA
- Zielona Gora (EPZG) SRA

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding which will include the boundaries mentioned above will appear in Jeppesen NavData for cycle 2107, effective 15 July 2021. Until then this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/alerts.jsp>).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.