

## **SERVICE ADVISORY**

**NO.: 21101 Rev A**

**TO:** GI-102A and GI-106A Owners and Operators  
**DATE:** September 23, 2021  
**SUBJECT:** GI-102A and GI-106A End of Service Life

---

### **PRODUCTS AFFECTED**

Garmin GI-102A and GI-106A units are affected.

### **ISSUE**

Repair services (including exchanges) are discontinued for the GI-102A and GI-106A effective 10/1/21.

We sincerely regret discontinuing service or support on any Garmin product. GI 102A and GI 106A units may still be serviced by the manufacturer. Contact Mid-Continent Instruments and Avionics for details.

The GI-106B is available as a replacement.

<https://buy.garmin.com/en-US/US/p/552213>