



1200 E. 151st Street
 Olathe, KS 66062
 913-397-8200

SERVICE ADVISORY

NO.: 2195 Rev A

TO: Garmin GIA 64 Owners and Operators
DATE: September 15, 2021
SUBJECT: GIA 64 COM Receiver

PRODUCTS AFFECTED

Garmin GIA 64 units purchased or installed since April 2021 listed in the link below are affected.

<https://support.garmin.com/en-US/?faq=m849xu3Exl8UywVgEB3EU9>



NOTE

GIA 64 unit serial numbers can be viewed on the AUX - System Status page.

The screenshot shows the AUX - SYSTEM STATUS page with the following data:

LRU INFO	STATUS	SERIAL NUMBER	VERSION
ADF1	✗	-----	-----
COM1	✗	-----	-----
COM2	✗	-----	-----
GDC1	✗	-----	-----
GDL69	✓	0000001	0.00
GEA1	✗	-----	-----
GIA1	✓	0000001	0.50
GIA2	✗	0000002	0.50
GMA1	✗	-----	-----
GMU1	✗	-----	-----
GPS1	✓	0000001	3.0
GPS2	✗	0000002	3.0
GRS1	✗	-----	-----
GS1	✗	-----	-----
GS2	✗	-----	-----
GSA PTCH CTL	✗	-----	-----

AIRFRAME	Value
AIRFRAME	Mooney Acclam
SYS SOFTWARE VERSION	0401.35
CONFIGURATION ID	4E97ED92
CRG PART NUMBER	
SYSTEM ID	000000000
CHECKLIST	NOT AVAILABLE

MFD1 DATABASE	Value
NAVIGATION - INTERNAL	
REGION	WORLDWIDE
CYCLE	1409
EFFECTIVE	21-AUG-16
EXPIRES	18-SEP-16
Copyright 2014, Jappesen Sanderson, Inc.	
NAV STANDBY - UNKNOWN	
REGION	NOT AVAILABLE
CYCLE	
EFFECTIVE	__-__-__
EXPIRES	__-__-__

© 2021 Garmin Ltd. or its subsidiaries.

This work is licensed under a [Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).

ISSUE

Some GIA 64 units may experience a COM receiver failure and/or open squelch.

**NOTE**

The COM transmitter is not affected by this issue.

ACTION

Be aware the COM receiver may fail and or squelch may stay open.

Contact your local Garmin dealer for compliance with Garmin Service Bulletin 2194.