



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## SERVICE ADVISORY

NO.: 20126 Rev B

**TO:** G5 Owners and Operators  
**DATE:** November 10, 2021  
**SUBJECT:** G5 Battery Pack  
**REVISION B:** Updated for the Ver. 3 Battery Pack

---

### **PRODUCTS AFFECTED**

All G5 products are affected.

### **ISSUE**

The 010-12493-00 G5 Battery Pack and the 010-12493-01 G5 Battery Pack Ver. 2 are now replaced by the 010-12493-02 G5 Battery Pack Ver. 3. The -02 has the same form, fit, and function as the -00 and the -01 battery pack.

The -02 battery pack does require G5 Software Version 6.80 or later. Not upgrading to G5 Software Version 6.80 (or later) will result in a battery fault message.

### **ACTION**

Make sure all G5 units with a 010-12493-02 battery pack have G5 Software Version 6.80 or later.

© 2021 Garmin Ltd. or its subsidiaries.  
This work is licensed under a  
Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.