



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Garmin GFC 600 Owner and Operators  
**DATE:** December 7, 2021  
**SUBJECT:** Vertically Mounted GTA 82 Support Bracket  
**CERTIFICATION AUTHORIZATION:** STC SA01844WI

---

### **COMPLIANCE**

Recommended: Garmin recommends compliance with this service bulletin within the next 100 hours or the next annual inspection whichever occurs first.

### **PURPOSE**

A new support bracket improves the stiffness of the GTA mounting structures and helps to prevent possible fatigue failure when subjected to long duration exposure to vibration.

### **PRODUCTS AFFECTED**

GTA 82 units installed per the GFC 600 Installation Manual Addendum TBM 700/700N (190-01937-08) Revision 4 and earlier are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.