

1200 E. 151<sup>st</sup> Street Olathe, KS 66062 913-397-8200

#### **AVIATION SERVICE DOCUMENT NOTIFICATION**

TO: Garmin G1000 NXi Textron Aviation Inc. (Beechcraft) King Air model C90A,

C90GT, C90GTi Owner and Operators

**DATE:** December 21, 2021

SUBJECT: G1000 NXi STC Audio Wiring Update for C90 Series Aircraft

**CERTIFICATION** 

**AUTHORIZATION:** STC SA01456WI-D Rev 20

### **COMPLIANCE**

Mandatory: This STC Service Bulletin must be accomplished no later than December 31, 2022

# **PURPOSE**

This service bulletin provides instructions for a wiring update to correct low audio levels for warnings as described in Garmin Service Alert 21121

# **PRODUCTS AFFECTED**

Textron Aviation Inc. (Beechcraft) King Air model C90A, C90GT, C90GTi aircraft equipped with **all** of the following:

- G1000 NXi Integrated Flight Deck per STC SA01456WI-D
- G1000 NXi System Software Version 3557.00 or 3557.01
- GMA 1360 Audio Panels
- Aural Tone Generators

#### WARRANTY INFORMATION

This Service Bulletin is warranty reimbursable with a deadline of December 31, 2022 after which this upgrade will no longer be reimbursable for labor.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.