



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GI 275 Owner and Operators
DATE: January 7, 2022
SUBJECT: GI 275 Multi-Function Instrument Expansion Software Version 2.43
CERTIFICATION AUTHORIZATION: STC SA02658SE MDL Revision 16

COMPLIANCE

MANDATORY: STC Service Bulletin 22002 is mandatory for Dual GI 275 Multi-function Instrument systems (011-04489-10, 011-04489-20) installed as the only means to determine aircraft attitude under the GI 275 Part 23 AML STC SA02658SE MDL Revision 15 or earlier.

Compliance with the service bulletin is recommended for all other installations.

PURPOSE

This STC Service Bulletin provides notification of STC SA02658SE Master Drawing List Revision 16 update which includes GI 275 Expansion Board Software improvement to provide additional robustness for the GI 275 ADAHRS solution. Refer to Garmin Service Alert 2182.

PRODUCTS AFFECTED

All GI 275 units installed under Part 23 AML STC SA02658SE MDL Revision 15 or earlier are affected.



NOTE

Including GI 275 Multi-function Instruments with Expansion Software Version 2.42.

WARRANTY INFORMATION

This Service Bulletin is warranty reimbursable for GI 275 Multi-Function Instruments described in the Product Affected section only. Warranty reimbursement deadline is June 30, 2022.



NOTE

Installations completed after January 7, 2022 are not eligible for warranty reimbursement.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.