

# GARMIN®

## FliteCharts Data Alert 25061

**TO:** Users of all Garmin aviation products and Garmin Pilot™ using the Australia or South Pacific FliteCharts® database

**DATE:** September 10, 2025

**CYCLE:** 2509

**SUBJECT:** Missing Departures

---

### **PRODUCT AFFECTED**

Australia and South Pacific FliteCharts cycle 2509 (effective September 04, 2025) are affected.

### **DESCRIPTION**

The following charts at Amberley (YAMB), Queensland, Australia were excluded:

- SID RWY 15/33 SOUTH (RNAV)
- SID RWY 15/33 NORTH WEST (RNAV)

### **PILOT ACTION**

Be aware the SID RWY 15/33 SOUTH (RNAV) and SID RWY 15/33 NORTH WEST (RNAV) charts are missing at Amberley (YAMB), Queensland, Australia in Australia or South Pacific FliteCharts for cycle 2509.

### **RESOLUTION**

The charts will be included in cycle 2510 of the Australia and South Pacific FliteCharts databases for applicable Garmin aviation products and in Garmin Pilot. Cycle 2510 FliteCharts databases are effective October 02, 2025 and will be available September 30, 2025.

*Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.*

*Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](https://flygarmin.com) and select "Aviation Data Error Report."*