

GARMIN[®]

Navigation Data Alert 25081

TO: Users of the Garmin Navigation Database
DATE: November 7, 2025
CYCLE: 2511
SUBJECT: Incorrect Holding Leg Length

PRODUCT AFFECTED

The Garmin Navigation Database cycle 2511 (effective October 30, 2025) is affected.



NOTE

The data alert does not apply to the Jeppesen NavData database.

DESCRIPTION

The PWAK (Wake Island Airfield) Airport contains incorrect missed approach holding leg lengths in the following procedures:

- RNAV (GPS) RWY 10
- RNAV (GPS) RWY 28

The missed approach holding fixes (DUPUF and NONEY) have a 4-minute holding length instead of the published 4NM distance.

PILOT ACTION

Use the procedures with caution.

RESOLUTION

The procedure will be corrected in the 2512 cycle of the Garmin Navigation Database, effective November 27, 2025.

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](https://www.flygarmin.com) and select "Aviation Data Error Report."