

GARMIN[®]

Navigation Data Alert 26016

TO: Users of the Garmin Navigation Database
DATE: January 28, 2026
CYCLE: 2601
AIRPORT: MMMY (Gral. Mariano Escobedo)
SUBJECT: Incorrect Starting Fix on Approach Transition

PRODUCT AFFECTED

Cycle 2601 of the Garmin Navigation Database (effective 22 JAN 2026 to 19 FEB 2026) is affected.



NOTE

This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

The MMMY airport contains an incorrect starting fix on an approach transition for procedure VOR Y RWY 12.

The approach transition coming from airway UJ45 incorrectly starts at the fix ELERA which is not on the airway. The correct approach transition starts at the 18 DME fix on the 187 degree radial from the MTY VOR/DME.

PILOT ACTION

Use the procedure with caution.

RESOLUTION

The procedure will be corrected in the 2602 cycle of the Garmin Navigation Database.

**THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS
UTILIZING THE GARMIN NAVIGATION DATABASE**

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](https://flygarmin.com) and select "Aviation Data Error Report."