

FliteCharts Data Alert

TO: Users of all Garmin aviation products and Garmin Pilot™ using the Brazil FliteCharts® database

DATE: May 20, 2026

CYCLE: 2605

SUBJECT: Outdated Approach & Departure Charts for Ponta Porã International (SBPP) and Aerodrome Chart at Campo Fontenelle (SBYS) in Brazil

DESCRIPTION

The charts from the 2605A0 amendment for Ponta Porã International (SBPP) in Ponta Porã, Brazil and Campo Fontenelle (SBYS) in Pirassununga, Brazil were not incorporated into Brazil FliteCharts cycle 2605, effective May 14, 2026.

PILOT ACTION

Use caution when referencing the following charts in Brazil FliteCharts for cycle 2605:

Airport	Chart Type	Chart Name
SBPP	IAC	NDB RWY 04
SBPP	IAC	NDB RWY 22
SBPP	IAC	RNP RWY 04
SBPP	IAC	RNP RWY 22
SBPP	SID	OMNI RWY 04/22
SBPP	SID	RNAV ABAFT 1A RWY 04
SBPP	SID	RNAV EGODO 1A RWY 22
SBYS	ADC	Aerodrome Chart

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

RESOLUTION

The affected charts will be corrected in cycle 2606 of the Brazil FliteCharts database for applicable Garmin aviation products and in Garmin Pilot. Cycle 2606 FliteCharts databases are effective June 11, 2026 and will be available June 9, 2026.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE BRAZIL FLITECHARTS DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."