

FliteCharts Data Alert

TO: Users of all Garmin aviation products and Garmin Pilot™ using the United States, North America, US/Canada, US/Latin America, US with Guided Visuals, or North America with Guided Visuals FliteCharts® databases

DATE: May 29, 2026

CYCLE: 2605 and 2606

SUBJECT: Corrected Airport Diagram for St. George Regional (KSGU), St. George, UT

DESCRIPTION

The FAA has advised Garmin that the digital-Terminal Procedures Publication, effective May 14, 2026, contains incorrect taxiway identifiers at St. George Regional (KSGU) in St. George, UT. Taxiway “A3” should be labeled “A4” and Taxiway “A4” should be labeled “A5” on the airport diagram.

The original safety alert and corrected chart can be seen at the following link:

https://www.faa.gov/AIR_TRAFFIC/FLIGHT_INFO/AERONAV/SAFETY_ALERTS/media/TERM_26-03_SA_SGU_AD.pdf

PILOT ACTION

Exercise caution when using the airport diagram at St. George Regional (KSGU), St. George, UT in FliteCharts for cycles 2605 and 2606.

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

RESOLUTION

The chart will be corrected in cycle 2607 of the FliteCharts databases for applicable Garmin aviation products and in Garmin Pilot. Cycle 2607 FliteCharts databases are effective July 9, 2026, and will be available July 7, 2026.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING A FLITECHARTS DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select “[Aviation Data Error Report](#).”