

SmartCharts Alert

TO: Users of Garmin Pilot™ Mobile US and Worldwide for iOS
DATE: May 29, 2026
CYCLE: 2605 and 2606
SUBJECT: Incorrect Taxiway Identifiers at St. George Regional (KSGU), St. George, UT

DESCRIPTION

The FAA has advised Garmin that the digital-Terminal Procedures Publication, effective May 14, 2026, contains incorrect taxiway identifiers at St. George Regional (KSGU) in St. George, UT. Taxiway “A3” should be labeled “A4” and Taxiway “A4” should be labeled “A5” on the airport diagram.

The original safety alert and corrected chart can be seen at the following link:

https://www.faa.gov/AIR_TRAFFIC/FLIGHT_INFO/AERONAV/SAFETY_ALERTS/media/TERM_26-03_SA_SGU_AD.pdf

PILOT ACTION

Exercise caution when referencing the Garmin SmartCharts airport diagram at St. George Regional (KSGU), St. George, UT for cycle 2605 and cycle 2606.

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

RESOLUTION

This SmartCharts airport diagram will be corrected in cycle 2607, effective July 9, 2026.

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select [“Aviation Data Error Report.”](#)