

GARMIN®

Navigation Data Alert 26108

TO: Users of the Garmin Navigation Database
DATE: July 13, 2026
CYCLE: 2607
SUBJECT: Incorrect Speed on Departure

PRODUCT AFFECTED

Cycle 2607 of the Garmin Navigation Database (effective 09 JUL 2026 to 06 AUG 2026) is affected.
This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

Incorrect speed on departure.

Airport	Procedure	Correction
CAJ3	BOXAT5 Departure	The correct initial speed is At or Below 200 kts.

PILOT ACTION

Use the procedure with caution.

RESOLUTION

The procedure will be corrected in the 2608 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](https://flygarmin.com) and select "[Aviation Data Error Report](#)."