

# GARMIN®

## SmartCharts Data Alert 26094

**TO:** Users of US and Worldwide Garmin Pilot™ Mobile for iOS and Garmin Pilot™ Web

**DATE:** July 2, 2026

**CYCLE:** 2606

**SUBJECT:** Incorrect Missed Approach Icon for ILS or LOC RWY 05 at KSME.

---

### **PRODUCT AFFECTED**

The Garmin SmartCharts procedure for ILS or LOC RWY 05 at KSME, Somerset, KY, shown in Garmin Pilot Mobile iOS and Garmin Pilot Web is affected.

### **DESCRIPTION**

When the ILS minima is selected, the 4th icon in the details missed approach icons or the quick reference missed approach icons does not indicate a navaid facility for the DME shown.

When the LOC or Circling Minima is selected, the 4th icon in the details missed approach icons or the quick reference missed approach icons indicates an incorrect navaid facility for the DME shown.

The correct navaid facility for SITOW/13.5 DME is I-SME.

### **PILOT ACTION**

Use caution when viewing the missed approach icons for the procedure listed above.

SITOW/13.5 DME is from I-SME.

### **RESOLUTION**

This will be corrected in cycle 2607.

### **THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE**

*Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.*

*Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](https://flygarmin.com) and select "[Aviation Data Error Report](#)."*