

GARMIN®

Navigation Data Alert 26107

TO: Users of the Garmin Navigation Database
DATE: July 10, 2026
CYCLE: 2607
SUBJECT: France MIAC N08/26 NON AIRAC cycle 2607 was Received Late

PRODUCT AFFECTED

Cycle 2607 of the Garmin Navigation Database (effective 09 JUL 2026 to 06 AUG 2026) is affected.

DESCRIPTION

The following data is out of date.

Navaid	Error
BST TACAN	Magvar changed to 0° West from 1° West
BST NDB	Magvar changed to 0° West from 1° West
LU NDB	Magvar changed to 3° East from 2° East

Airport	Procedures	Error
LFTH	ILS ou LOC RWY05	Renamed ILS X ou LOC X RWY 05
LFRL	TACAN RWY05	Procedure Magvar changed to 0° West from 1° West. All courses adjusted by one degree
	NDB RWY05	
	NDB MVL RWY23	
	TACAN RWY05	

Airport	Procedures	Error
LFMC	FNA VOR Z RWY09	Procedure Magyar changed to 3° East from 2° East. All courses adjusted by one degree
	VOR Y RWY09	
	VOR X RWY09	
	GILON 1 Departure	
	GILON 2 Departure	
	RUBIT 1 Departure	
	RUBIT 2 Departure	
	CUERS1 Departure	
	CUERS2 Departure	
	NIMPA1 Departure	
	NIMPA2 Departure	
	NEOUL1 Departure	
	NEOUL2 Departure	
	SUSUK1 Departure	
	SUSUK2 Departure	
	CUEOB1 Departure	
	CUEOB2 Departure	

PILOT ACTION

Use the procedures with caution

RESOLUTION

The procedures will be corrected in the 2608 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to Fly-Garmin.com and select [“Aviation Data Error Report.”](#)